

Oil Field Environmental Incident Summary

Incident: 20160213200712 **Date/Time of Notice:** 02/13/2016 20:07
Responsible Party: ENERPLUS RESOURCES USA CORPORATION
Well Operator: ENERPLUS RESOURCES USA CORPORATION
Well Name: HILO 148-94 23B-2H TF
Field Name: MCGREGORY BUTTES **Well File #:** 20983
Date Incident: 2/13/2016 **Time Incident:** 09:00 **Facility ID Number:**
County: DUNN **Twp:** 148 **Rng:** 94 **Sec:** 23 **Qtr:**
Location Description: Prairie

Submitted By: Tony Lucero **Received By:**

Contact Person: Chuck Antle
US BANK TOWER
950 17TH ST STE 2200
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Stuffing Box Leak

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

None

Areal Extent:

Remained confined to well pad.

Potential Environmental Impacts:

Remained confined to well pad.

Action Taken or Planned:

Shut in well and repaired stuffing box.

Wastes Disposal Location: At an approved disposal site.

Agencies Involved: BLM, BIA and Three Affiliated Tribes

Updates

Date: 2/16/2016 **Status:** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.